





REV. 10-15-21



The Architect is not responsible for the design of the building and other structures shown on this plan. The Architect is not responsible for the design of the building and other structures shown on this plan. The Architect is not responsible for the design of the building and other structures shown on this plan.

ENGINEER:

FLOOR PLANS
New Building for:
FOUNTAINHEAD IRRIGATION
Tilco Drive
Frederick, Maryland 21701

DATE	REVISION LOG
DATE	NO.
08/05/2021	1
21-014	2
PERMIT	3
DRAWN BY	4
CHECKED BY	5



A-1.1